# VAS5234 TROUBLE-SHOOTING

## FAULTPOSSIBLE CAUSESOLUTIONS

1		
Pre-set unit operating pressure of about 5 bar (air pressure gauge) is not achieved during the "SELF-CHECK" operating mode or breaks down cyclically.	Air pressure in workshop network is to low.	Set pressure in workshop network between 5-12 bar (75-175psi).
	Filter/Controller assembly is faulty.	Exchange Filter/Controller CRP 1898024
	Filtration capacity of the Filter/Controller exceeded.	Clean filtration element with compressed air or replace.

2

<u></u>		
The ball inserted in the	Controller assembly faulty.	Exchange assembly unit.
sight glass to indicate the		CRP1898027
flow fails to raise in the	Pump assembly faulty.	Exchange pump unit
"SELF-		CRP 1898060
CHECK operating mode.		

### FAULT POSSIBLE CAUSE SOLUTIONS

3		
In the "SELF-CHECK" operating mode small bubbles appear at more or less regular intervals in the sight glass.	Leak in the suction hose between the Shut Off Unit and the Pump assembly.	Repair leak.
	Leak in the Shut Off Unit and/ or the Pump.	Replace pertinent assembly! NOTE!If the leak cannot berepaired unit has to bestopped immediately.

1

4		
The unit fails or is to slow	Leak in the collection flask,	Repair leak.
in removing the brake fluid	the hoses or couplings.	
from the brake fluid		
reservoir of the vehicle.		Replace assembly unit
Approximate time required:	Vacuum Unit faulty.	CRP1898025
about 30 seconds depending		
on the type of top-up		
container.		

5

5		
When filling the brake fluid	Controller assembly faulty	Replace assembly unit.
reservoir filling pressure		CRP 1898027
fails to be produced after		
about 30 seconds or a filling		
pressure exceeding 3 bar is		
achieved.		

6

0		
During the flushing	Filtration capacity has come	Replace filter.
procedure (at the front of	to its end.	CRP1899986
the vehicle) the fluid		
,	Through flow quantity	Reduce the opening of the
pressure on the "FLUID"	excessive.	bleeding valve on the
pressure gauge drops about	CACC551VC.	e
0.2 bar below the set level.		vehicle

## FAULT 7

## **POSSIBLE CAUSE** SOLUTIONS

1		
	The position of the float in	Move float with the
	the Shut Off unit is set to	"REFILL" button to a
The unit switches off even	low.	position shortly before its
through an adequate quantity		upper limit.
of brake fluid is available in	Leak in the hose from the	Repair leak, possible
the drum.	suction pipe to the Shut Off	replace coupling to suction
	Unit	pipe.
	Shut Off Unit assembly	Exchange assembly
	faulty.	CRP1898026

8		
Noticeable leak of fluid	Gasket elements of the	Replace assembly.
from the vent bores of the	Pump assembly are worn	CRP1898060
Pump	out.	