


## T10607/2 Spare Parts

TKR Group Inc – North America has partnered with SBS and VW GoA to bring spare parts (O-Rings) of T10607/2 to the U.S.



When repairing the T10607/2 you will need three of the same type O-Ring to conclude the repair. These O-Rings will be available through the VW Snap-on Business Solutions Website or Call SBS Customer Service at 1-800-892-9650 for purchase.

Qty	Part Nr.	Description
3	TKR99-000592	Replacement O-ring